



- Real Estate Inspections
- Infrared Thermography
- Stucco Inspections
- Diagnostic Inspections
- and more

*Providing Peace of Mind  
One home at a time  
Since 1989*

## **INSPECTION GROUP**

FIG Services LLC d/b/a FOX INSPECTION GROUP  
Property Inspection Report # 090309rs  
11227 Endicott Lane Houston, TX 77035  
(Office) 713.723-3330 (Email) [office@foxinspectiongroup.com](mailto:office@foxinspectiongroup.com)

---

TREC Professional Inspectors # 1718, 3648, 5570, 6000, 6389, 7158, 7244, 7248, 7406, 7415, 7466, 7657, 7932, 9355, 9378, 9459

NAWT – Septic Inspector # 111984 IC

SBCCI Registered Building Inspector #5939

SBCCI Registered Mechanical Inspector # 1739

Exterior Design Institute (EDI) # TX-116, TX-119

ICC Building Inspectors # 1052678-B5, #5294898-B5

State of Texas Registered Code Enforcement Officer # CE1858

ICC Residential Combination Inspectors # 1052678-R5, #5294898-R5

ICC Residential Building Inspectors # 5167093-B1, #5294898-B1

ICC Mechanical Inspectors # 1052678-M5, #5294898-M5, 5230842-M1

Texas Department of Insurance VIP Certificates #20110061045, # 33901081163

SBCCI Registered One & Two Family Dwelling Code Certified Inspector #1863 & #2185

ITC Certified Level 1 Infrared Thermographers #8661, #8662, #8663, #8692, #8693, #8694, #26034, #26504, #26505

### **2002 Humble Home Inspection Report**

# ***PROPERTY INSPECTION REPORT***

---

**Prepared For:** client  
(Name of Client)

**Concerning:** 2002 Home, Humble, Texas 77338  
(Address or Other Identification of Inspected Property)

**By:** Ruben Santillan (TREC #5570)  
(Name and License Number of Inspector)

March 9, 2009  
(Date)

---

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions. If any item or comment is unclear, you should ask the inspector to clarify the findings. It is important that you carefully read ALL of this information.

This inspection is subject to the rules ("Rules") of the Texas Real Estate Commission ("TREC"), which can be found at [www.trec.state.tx.us](http://www.trec.state.tx.us).

The TREC Standards of Practice (Sections 535.227-535.231 of the Rules) are the minimum standards for inspections by TREC-licensed inspectors. An inspection addresses only those components and conditions that are present, visible, and accessible at the time of the inspection. While there may be other parts, components or systems present, only those items specifically noted as being inspected were inspected. The inspector is not required to move furnishings or stored items. The inspection report may address issues that are code-based or may refer to a particular code; however, this is NOT a code compliance inspection and does NOT verify compliance with manufacturer's installation instructions. The inspection does NOT imply insurability or warrantability of the structure or its components. Although some safety issues may be addressed in this report, this inspection is NOT a safety/code inspection, and the inspector is NOT required to identify all potential hazards.

In this report, the inspector will note which systems and components were Inspected (I), Not Inspected (NI), Not Present (NP), and/or Deficient (D). General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing parts, and unsuitable installation. Comments may be provided by the inspector whether or not an item is deemed deficient. The inspector is not required to prioritize or emphasize the importance of one deficiency over another.

Some items reported as Deficient may be considered life-safety upgrades to the property. For more information, refer to [Texas Real Estate Consumer Notice Concerning Recognized Hazards, form OP-I](#).

This property inspection is not an exhaustive inspection of the structure, systems, or components. The inspection may not reveal all deficiencies. A real estate inspection helps to reduce some of the risk involved in purchasing a home, but it cannot eliminate these risks, nor can the inspection anticipate future events or changes in performance due to changes in use or occupancy. It is recommended that you obtain as much information as is available about this property, including any seller's disclosures, previous inspection reports, engineering reports, building/remodeling permits, and reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should also attempt to determine whether repairs, renovation, remodeling, additions, or other such activities have taken place at this property. It is not the inspector's responsibility to confirm that information obtained from these sources is complete or accurate or that this inspection is consistent with the opinions expressed in previous or future reports.

Items identified in the report do not obligate any party to make repairs or take other action, nor is the purchaser required to request that the seller take any action. When a deficiency is reported, it is the client's responsibility to obtain further evaluations and/or cost estimates from qualified service professionals. Any such follow-up should take place prior to the expiration of any time limitations such as option periods. Evaluations by qualified tradesmen may lead to the discovery of additional deficiencies

---

which may involve additional repair costs. Failure to address deficiencies or comments noted in this report may lead to further damage of the structure or systems and add to the original repair costs. The inspector is not required to provide follow-up services to verify that proper repairs have been made.

Property conditions change with time and use. For example, mechanical devices can fail at any time, plumbing gaskets and seals may crack if the appliance or plumbing fixture is not used often, roof leaks can occur at any time regardless of the apparent condition of the roof, and the performance of the structure and the systems may change due to changes in use or occupancy, effects of weather, etc. These changes or repairs made to the structure after the inspection may render information contained herein obsolete or invalid. This report is provided for the specific benefit of the client named above and is based on observations at the time of the inspection. If you did not hire the inspector yourself, reliance on this report may provide incomplete or outdated information. Repairs, professional opinions or additional inspection reports may affect the meaning of the information in this report. It is recommended that you hire a licensed inspector to perform an inspection to meet your specific needs and to provide you with current information concerning this property.

---

---

### ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

---

---

**Highest priority items are printed in bold print and/or are in boxes**

**All commented items should be repaired or addressed to client's satisfaction PRIOR TO CLOSING.**

Items that are underlined should be addressed to prevent more extensive damage and should be a priority item or indicate non-compliance with current building standards

*Comments in italics are generally FYI (for your information) and don't require any action.*

---

---

**For Reference:** The front of unit faces West.

**Description:** 2 story, wood framed, single family residence; Brick / Hardi-plank / wood exterior; Composition roof; Attached garage.

### I. STRUCTURAL SYSTEMS

- 

#### A. Foundations

Type of Foundation(s):

Slab

Comments:

*Performing intended function. No evidence suggesting significant foundation movement at time of inspection.*

*Spalling (i.e., corner pops) at one or more corner(s), Corner spalling is common to slab foundations and does not affect the structural integrity of the foundation.*



- 


#### B. Grading & Drainage

Comments:

*Buyer's note; ensure flower bed soil does not rise above joint between concrete and brick pavers of exterior patios, wood destroying insects have been known to gain entry between pavers and concrete patio and migrate to house.*



Drainage swale is not continuous, at sides The drainage swale must be kept clear and continuously sloped in order to drain water properly



**C. Roof Covering Materials**

Type(s) of Roof Covering:


*Type of roof material observed to be composition over solid decking.*

Viewed From:

Roof Comments:


ROOF SURFACE:

The felt paper observed to be improperly installed under the drip edge. Felt paper should be laying over the metal drip edge to avoid possible moisture from getting trapped and damaging the fascia boards.



Valley shingles improper. In a closed valley, embed valley shingles in roofing cement.

Always clip the top corner of the valley shingles at a 45-degree angle. This prevents debris from getting caught in the shingles and accumulating in the valley, and it also directs water toward the valley centerline. For extra protection, install a self-adhering eaves membrane under valleys.



*Observed a “dead valley” roof configuration on roof top. This area is a potential source of debris buildup / water penetration and care should be taken to keep this area free of debris to facilitate rain water run off.*



**VISIBLE FLASHING:**


Lower side of flashing is not sealed down, wind driven rains can cause water penetration at the sidewall flashing over the garage. Evidence of water penetration observed in the garage directly over this area.



**ROOF PENETRATIONS: GOOD**

**EVIDENCE OF ROOF WATER PENETRATION:**

YES !!, Evidence of water intrusion observed in the garage directly under the dead valley area. The cause and remedy needs to be investigated and corrected as necessary. See pictures and comments above.



**RAIN GUTTERS & DOWNSPOUTS:**

Need general maintenance, Clean out debris / resecure to fascia board / tilt toward drains, seal leaks, etc.



Downspouts need splash blocks at bottoms to prevent soil erosion.

Observed water stains on fascia board on back side of rain gutters; indication water is running down back side of rain gutter which leads to wood rot.



Gutter fasteners observed to be pulling loose in various locations.

Downspout lower turn observed to be damage and full of debris on the east side of the structure.

Fasteners pulling loose.



Lower turn damage, holding debris.



**D. Roof Structure & Attic**

Viewed From: *Inside accessible areas of attic*

Approximate Average Depth of Insulation: *8 inches.*

Comments:

ROOF STRUCTURE AND FRAMING: GOOD

ATTIC INSULATION: GOOD

ATTIC ACCESS, LADDERS AND SERVICE WALKS:

*Not all areas of attic were accessible to inspection.*

*Stairway to attic is not sealed, recommend client consider weather stripping to seal gaps and prevent loss of conditioned air to attic as well as insulating stairway if not done already.*



I	NI	NP	D	Inspection Item
---	----	----	---	-----------------

ATTIC VENTILATION & SCREENING: GOOD

**E. Walls (Interior & Exterior)**

Comments:

**INTERIOR:**

*Client Advisory: No moisture, mold and /or indoor air quality (IAQ) tests were performed. The inspector is not qualified / certified for such evaluations / studies. The client should be aware that various fungi, molds and mildew flourish in such an environment provided by water intrusion events, excessively moist conditions and / or water damaged conditions. A growing concern to date includes the adverse effect on indoor air quality and the potential for inherent health hazards. If concerned the client is advised to contact a qualified IAQ Professional for further evaluations of this property.*

*Evidence house and/or garage has been treated for wood destroying insects in the past. Final determination of structurally significant damage to wood members (if any) cannot be determined without removal of wall coverings. Recommend client obtain additional information from seller regarding extent and location of previous infestation, chemical & company used, warranty if applicable, etc.. Fox Inspections specifically excludes hidden / latent damage if present (we cannot see thru walls!).*

Water stains / damage or repairs observed; garage. Low moisture meter readings were taken at the time of this inspection. The cause and remedy should be investigated and corrected as necessary.


**EXTERIOR:**

*Bushes / trees / foliage should not contact siding of house to prevent wood rot and/or insect access.*

Wood rot observed on areas of house / garage.





Most wood siding installation requirements specifically state “ Leave 2” clearance between roofing and bottom edge of siding to prevent wood rot. Did not observe the normal 2” clearance from roof surface



Metal lintel(s) over window/door openings are not flashed as required by current building standards. Ref: IRC 2003 Section R703.7.5 Stone and Masonry Veneer | Flashing.

Metal lintel(s) over window/door openings are not painted.



EVIDENCE OF WATER PENETRATION:

YES !!, Evidence of water intrusion observed adjacent to the front door, and upstairs north east bedroom at the window. These areas should be closely monitored and repaired if necessary.




F. Ceilings & Floors

Comments:

CEILINGS:

Water stains observed on ceiling near air duct, indication of possible damage insulation on metal duct allowing warm attic air to condense on cold sheet metal and drip onto sheetrock; master bedroom.

Observed possible mold / black stuff ( master near register ) which may be a concern due to increased awareness of environmental issues associated with molds. Recommend removal of all sheetrock containing visible mold growth plus an additional 2 feet surrounding area. *This company does not inspect for and is not qualified to render opinions on any type on environmental or other bio-hazards. If this is a concern or potential concern, Fox Inspections recommends contacting a qualified professional of your choice for further information / investigation.*



FLOORS: GOOD

**G. Doors (Interior & Exterior)**

Comments:

**INTERIOR:**

Missing or non-functioning door stop behind one or more doors to prevent damage to sheetrock.

**EXTERIOR: GOOD**

*Prudent buyers replace/rekey exterior locks upon taking possession of property.*

**GARAGE: GOOD**

**H. Windows**

Comments:

**WINDOWS:**

One or more screens are missing and/or damaged.

One or more window spring(s) were observed to be sprung/broken/detached. The window in the back middle bedroom will not stay in the open position due to the damage window guides. Springs broken in the northeast, and east middle bedrooms.



SAFETY GLASS IN HAZARDOUS LOCATIONS:GOOD

**I. Stairways (Interior & Exterior)**

Comments:

INTERIOR:GOOD

**J. Fireplace/Chimney**

Comments: No fireplace/chimney present.

**K. Porches, Balconies, Decks, and Carports**

Comments:

*Cracks in walkways, driveway and/or garage concrete observed, typical.*

**II. ELECTRICAL SYSTEMS**

**A. Service Entrance & Panels**

Comments:

150 AMP ELECTRICAL SERVICE PANEL NORTHEAST EXTERIOR:

Not all breakers are properly identified.

Dead front missing one or more securing screws. Need to ensure screws used do not have sharp / pointed ends that can penetrate live electrical wiring behind dead front and cause shock, fire, serious injury, and /or death.

*Did not observe installed AFCI (Arc Fault Circuit Interrupt) device protection, as required by current building standards, for all: family rooms, dining rooms, living rooms, parlors, libraries, dens, bedrooms, sunrooms, recreations rooms, closets, hallways, or similar rooms or areas. AFCI devices are intended to protect against fires caused by electrical arcing faults in the home's wiring. Arc faults are a common cause of residential electrical fires. Arc faults can be created by damaged, deteriorated, or worn electrical plugs, cords, and/or branch circuit conductors. As of September 1, 2008, the State of Texas has adopted the 2005 NEC, which includes this requirement, as the "minimum standard" for all non-exempt electrical work. Homes built prior to 2002, generally were not required to have arc fault protection. However, the current TREC standard of practice requires inspectors to indicate that a hazardous or deficient condition exists if any home does not have this protection, regardless of date the home was constructed*


SERVICE WIRING:

*Observed service type of wiring is aluminum.*

FEEDER WIRING:

*Observed feeder type of wiring is copper.*

*Did not observe anti-oxidant compound (grease) on the exposed aluminum feeder wiring.*



I	NI	NP	D	Inspection Item
---	----	----	---	-----------------

**B. Branch Circuits, Connected Devices and Fixtures**

Type of Wiring:

*Observed type of branch wiring is copper.*

Comments:

BRANCH WIRING: GOOD

FIXTURES:

Light(s) found to be not functioning. Probably just a burned out bulb, or it could be a broken fixture / switch or improper wiring. Including but not limited to; half bathroom, laundry area, downstairs hallway by half bathroom, upstairs northeast bedroom and closet.

Light not secured, living area above the master bedroom.



OUTLETS:

*Not all outlets were checked / inspected / accessible in furnished residence.*

*Outlets located in inaccessible areas (e.g., garage ceilings, exterior soffits, etc.) are not individually tested.*

*GFCI reset locations; kitchen 2, upstairs hall bathroom 1, and garage 1.*

**GFCI does not reset after tripping in the master bathroom.**


Did not observe GFCI protection of all outlets in required locations, including but not limited to; all bathrooms, all kitchen counter top outlets, wet bar locations, all exterior outlets, in garage, etc. This condition is a recognized safety hazard and is in need of repair.

One or more outlets in the following locations were not protected:



- Kitchen counter
- Kitchen island
- Bathrooms
- Garage  Exterior
- Wet bar  Laundry sink
- Pool area  Spa / hot tub
- Other:

**Ground fault interrupter**

the GFI circuitry within the outlet checks constantly for a difference between the current in the black and white wires. If there is a difference (even as little as 5 millamps), there is a current leak (possibly through your body) and the GFI shuts down the receptacle and other receptacles downstream.



Space between face plate and edge of electrical junction box exceeds ¼ inch allowable by code. Missing required spacer ( spark ring) on all kitchen / bath counter top outlets and switches with tile back splash. Reference NEC 370-20 & IRC E3806.5. In walls of concrete, tile or other noncombustible material, cabinets (outlet & switch boxes) and panel boards shall be installed so that the front edge of the cabinet will not set back of the finished surface more than 0.25 inch.



**SWITCHES:**

*Unknown control, mystery switch(s) found, recommend inquiring current resident regarding use/control; living area above the master bedroom.*

*Could not locate the switch for the attic light fixture at the time of this inspection.*

**EQUIPMENT DISCONNECTS: GOOD****SMOKE DETECTORS AND ALARMS:**

*Smoke detectors are tested using the manufacturer supplied test button only. This inspection does not include testing units with actual smoke.*

*The installation of smoke alarm(s) is required inside of all bedrooms and in any rooms designated for the purpose of sleeping, and outside within the proximity of the doors to those rooms. Test all alarms and detectors weekly or monthly per manufacture instructions. The installation of carbon monoxide (CO) detector(s) is required in homes with fuel-fired appliances at every floor elevation and any areas where fuel-fired equipment is located. The installation of Type ABC fire extinguisher(s) at the kitchen, laundry, and garage, if applicable, is also advised. Test all of these devices monthly. Install new batteries semi-annually. Initiate and practice plans of escape and protection for all occupants in case any emergencies arise. Failure to repair defective or install absent alarms, detectors, and other safety equipment immediately can result in serious injury or death. For further information about fire safety and CO poisoning, consult your local fire department and your equipment manufacture(s), and read these links: [www.cpsc.gov/CPSCPUB/PUBS/464.pdf](http://www.cpsc.gov/CPSCPUB/PUBS/464.pdf), [www.carbonmonoxidekills.com](http://www.carbonmonoxidekills.com), [www.nfpa.org/index.asp](http://www.nfpa.org/index.asp), and [www.usfa.dhs.gov/downloads/pyfff/inhome.html](http://www.usfa.dhs.gov/downloads/pyfff/inhome.html).*

Low battery chirp/sound emitted from one or more smoke detectors

I	NI	NP	D	Inspection Item
---	----	----	---	-----------------

### III HEATING, VENTILATION, AND AIR-CONDITIONING SYSTEMS

**A. Heating Equipment**

Type of System: *Forced air*

Energy Source: *Gas*

Comments:

HEATING UNIT:

Make: Carrier (2002)

Model #: 58STX110-10122

S/N: 3702A45114

The burner cover fasteners was not long enough to properly secure the burner cover.

Cover is currently loose and needs to be secured.




HOUSE HEATER EXHAUST VENT(S): GOOD

BLOWER(S): GOOD

**THERMOSTAT(S):**

Thermostat wiring not secured to attic unit(s), missing small fitting that secures wiring to cabinet to prevent pulling loose by service personnel or homeowner.



**B. Cooling Equipment**

Type of System: Forced air, split system


Comments:

**CONDENSING UNIT:**

Make: Carrier (2002)  
Model #: 38BRC060-341 (5 tons)  
S/N: 4902E10960

*Recommend painting expanding foam sealant where A/C Freon lines pass through wall to protect it from degradation due to UV light exposure.*

Refrigerant line insulation damage observed at the outside condenser.



I	NI	NP	D	Inspection Item
---	----	----	---	-----------------

EVAPORATOR COIL:

Temperature Differential: = 16.0  
7 5 degrees.  
5 9

Make: Carrier (2002)  
Capacity: 5 tons

CONDENSATION DRAIN PAN / DRAIN LINES: GOOD

C. Duct System, Chases, and Vents

Comments:

RETURN DUCTS CHASES AND VENTS: GOOD

SUPPLY DUCTS CHASES AND VENTS:

Observed possible mold / black stuff on air supply grills / vents which may be a concern due to increased awareness of environmental issues associated with molds. This company does not inspect for and is not qualified to render opinions on any type of environmental or other bio-hazards. If this is a concern or potential concern, Fox Inspections recommends contacting a qualified professional of your choice for further information / investigation.

Observed several / multiple areas in attic where flex duct touch and are missing required 1" clearance from other ducts to prevent condensation between ducts that touch. Recommend general maintenance to flex ducts in attic, Re-support where needed, seal/tape minor air leaks, repair torn/damaged vapor seal, etc..



### IV. PLUMBING SYSTEM

**A. Water Supply System and Fixtures**

Location of water meter: *West of property*

Location of main water supply valve: *West*

Static water pressure reading: *44 psi*

Comments:

**WATER SUPPLY PLUMBING:**


*Water supply piping observed to be predominantly plastic.*

*Water softener, treatment and filtration type equipment is not checked / inspected.*

**COMMODOES:**

Float device observed to be damage to the upstairs commode.

Tank water level too high; half bathroom.



SINKS: GOOD

FAUCETS: GOOD

**TUB(S):**

Grout / caulking needed at vertical tile corners, cracks in tile and/or mortar between tiles, and where tile meets tub to prevent water entry behind wall.

**SHOWER(S):**

*24 hour shower pan test specifically excluded.*

Grout / caulking needed at vertical tile corners, cracks in tile and/or mortar between tiles, to prevent water entry behind wall.

I	NI	NP	D	Inspection Item
---	----	----	---	-----------------

**LAUNDRY CONNECTIONS: GOOD**

*Recommend use of stainless steel wire braided "no burst" clothes washer water supply lines to reduce chance of water damage.*

**EXTERIOR HOSE BIBS: GOOD**

**B. Drains, Wastes and Vents**

Comments:

*Hydrostatic pressure test of sewer lines specifically excluded.*

**DRAIN, WASTE, VENT PLUMBING:**

*Observed to be predominantly plastic.*

*There were no plumbing access / inspection panels behind one or more tub(s). Overflow gaskets and drains not checked. Recommend installation of bath plumbing access panels where possible.*

**C. Water Heating Equipment**

Energy Source: *Electric*

Capacity: *50 Gallons*

Comments:

**WATER HEATING UNIT(S): GOOD**

**TEMPERATURE & PRESSURE RELIEF VALVE(S):**

*Did not check operation since valve(s) over 3 years old and manufacture recommends replacement of T&P valves over 3 years of age.*

**D. Hydro-Massage Therapy Equipment**

Comments: *No equipment present.*

I	NI	NP	D	Inspection Item
---	----	----	---	-----------------

**V. APPLIANCES**

**A. Dishwasher**

Comments: No deficiencies observed.

**B. Food Waste Disposer**

Comments: No deficiencies observed.

**C. Range Exhaust Vent**

Comments: No deficiencies observed.

**D. Ranges, Cooktops, and Ovens**

Comments: No deficiencies observed.

RANGE/COOKTOP: GAS

OVEN: GAS

*Timer and cleaning cycles not checked*

**E. Microwave Oven**

Comments: No microwave present.

**F. Trash Compactor**

Comments: *Not present at time of inspection.*

**G. Mechanical Exhaust Vents and Bathroom Heaters**

Comments: No deficiencies observed.

**H. Garage Door Operator(s)**

Comments: No garage door present.

*Remote control hand held units were not checked.*

**I. Doorbell and Chimes**

Comments: No deficiencies observed.

**J. Dryer Vents**

Comments: No deficiencies observed.

*Recommend periodic cleaning dryer venting duct of lint to reduce risk of fire.*

### VI. OPTIONAL SYSTEMS

**A. Lawn and Garden Sprinkler Systems**

Comments: No system present.

**B. Outbuildings**

Comments: *Not present at time of inspection.*

**C. Outdoor Cooking Equipment**

Energy Source:

Comments: *Not present at the time of inspection*

**D. Gas Supply Systems**

Comments:

*Pressure test of gas lines specifically excluded.*

OBSERVED BRANCH LINES:

*Galvanized and/or black iron.*

APPLIANCE CONNECTIONS:

*Proper flex.*

Gas piping not sleeved as it passes thru masonry wall as required by Code [CABO 2608.3] IRC 2603.3.



I = Inspected    NI = Not Inspected    NP = Not Present    D = Deficiency

I	NI	NP	D	Inspection Item
---	----	----	---	-----------------

**E. Whole-House Vacuum Systems**  
Comments: *Not present at time of inspection.*

**F. Other Built-in Appliances**  
Comments: No other built in appliance inspected.

**G. Security Systems**  
Comments: *Not checked/inspected.*

***INTENT OF INSPECTION:***

It is the expressed intent and purpose of this report to inform you the client exclusively of the **visual ("eyeball") observations** and opinions made on the day of the inspection as to whether or not the structure, electrical, plumbing, and mechanical components of the subject property are performing the function for which they were intended to perform or are in need of immediate repairs. It is not within the intent and/or scope of this report to determine the insurability, habitability, suitability of use, economic life span, deferred maintenance issues, and/or issues unnamed in this report.

**This report is neither an expressed nor implied warranty and / or guarantee as to future life and/or performance of the items inspected**, but is intended to express the inspector's perceived impression of the apparent performance of the structure, electrical, plumbing, and mechanical components viewed on the date of the inspection. **Our intent is to reduce your risk associated with this transaction, however we cannot eliminate all risk nor assume your risk.**

***SCOPE OF INSPECTION:***

The content of this report is based solely upon "eyeball" observations of apparent performance. Opinions have been formed from the inspector's personal knowledge and experience and not upon any code requirements and/or performance standards. Compliance with any federal, state or local codes and/or other legal requirements is not within the scope or intent of this report.

***METHOD OF INSPECTION:***

The inspection methodology has not been of a formal engineered type of inspection; therefore, no soil, physical or geological testing or inspections were performed. Many of the structural, electrical, plumbing, and mechanical components were judged indirectly by the visible condition of the surfaces and/or components open to view. Observations were made both inside as well as outside of the structure; however, these observations were limited to only those areas open to view without moving any item, i.e.; inhabitants furniture, belongings or stored items which was blocking the view.

The inspector did not employ any instruments to aid in the inspection, **disassemble any component of an item checked**, (i.e.: disassemble a heating unit to inspect for a cracked heat exchanger), conduct extensive destructive testing, calculations, or removal of wall and floor covering unless noted in the body of this report.

***LIMITATION OF INSPECTION:***

The visual inspection method employed will generally produce a competent first impression assessment of the apparent past structural, electrical, plumbing, and mechanical components, provided refurbishing repairs have not been performed which would mask distress patterns normally produce by structural, electrical, plumbing, and mechanical components problems.

**Because the inspection procedure is visual only and was not intended to be diagnostic and/or technically exhaustive, an inherent residual risk remains that undiscovered problems exist and/or future problems will develop.**

There is no guarantee or warranty stated or implied that all defects have been found or that FIG Services, LLC d/b/a Fox Inspection Group will pay for the repair of any defect not discovered. The content of this report should be considered as an opinion of apparent performance of the items inspected and not engineering fact.

**THIS INSPECTION DOES NOT INCLUDE THE INSPECTION OF, SAMPLING FOR OR TESTING OF ANY SUBSTANCE CLASSIFIED OR OTHERWISE IDENTIFIED WITH OR AS A TOXIC SUBSTANCE AND/OR BIO-HAZARD OR WOOD DESTROYING INSECTS/ORGANISMS.**

*Client Advisory: No moisture, mold and /or indoor air quality (IAQ) tests were performed, The inspector is not qualified / certified for such evaluations / studies. The client should be aware that various fungi, molds and mildew flourish in such an environment provided by water intrusion events, excessively moist conditions and / or water damaged conditions. A growing concern to date includes the adverse effect on indoor air quality and the potential for inherent health hazards. If concerned the client is advised to contact a qualified IAQ Professional for further evaluations of this property.*

**EXPERT TESTIMONY / LITIGATION FINANCIAL COMPENSATION CLAUSE:**

In the event our services are needed at any time in the future as expert testimony or in a litigation case, client agrees at this time / in advance to financially compensate this firm for it's time and services.

Terms: Non-refundable retainer of \$2,500.00 upfront, Hourly rate of \$175.00 for any activities on our part for your case, including but not limited to; deposition, phone time, research, court time, travel time portal to portal, review of case prior to court appearance, etc. Balance due invoiced weekly, submitted Wednesday, payable the next Friday

**ARBITRATION / DISPUTE RESOLUTION**

In the event a dispute arises regarding an inspection that has been performed under this service agreement, Client(s) agree to notify FIG Services, LLC d/b/a Fox Inspection Group within ten (10) days of the time of discovery to give Fox Inspection Group a reasonable opportunity to re-inspect the property and resolved the dispute amicably. Upon the request of either party, all unresolved disputes relating to this agreement shall be submitted for arbitration in accordance with (AAA) American Association of Arbitrators then in effect with costs shared equally. This provision shall be specifically enforceable and damages for breach of this provision shall include but not limited to court costs and attorney's fees. Client agrees that FIG Services, LLC d/b/a Fox Inspection Group and it's agents liability, if any, shall be limited to the amount of the inspection fee paid for inspection. This limitation shall apply regardless of the cause of action or the legal theory pled or asserted specifically including, but not limited to, negligence.

FIG Services, LLC d/b/a Fox Inspection Group does not conduct re-inspection services for any reason. We are not in the business of certifying workmanship and/or warranting another company's repair work. Receipts and/or warranty for work performed should be obtained from the company or companies who have provided repairs.

Acceptance and/or reliance on this report shall constitute an acknowledgment, acceptance, and agreement by Client(s) as well as any spouse / significant other, and/or any assigns to all terms, conditions, exclusions and limitations of this report as well as an acknowledgment that the inspection includes only those items listed as inspected in the inspection report.